DFI LANPARTY NFII ULTRA B BIOS

Device: Name: Released: System:	DFI LANPARTY NFII ULTRA B BIOS 24 Nov 2004
File: Description:	 N24LDB24.BIN (LPNF2UBDB24.zip) REMARK: Only update for following CPU support. Please keep your BIOS in previous version if system works properly. 1. To also support FSB200 CPU with CPU clock at 100MHz. 2. To enhance the support of AMD 55-Watt Low Power CPU. Remarks: 1. Please input instrution as: AWDFLASH N24LDB24.BIN /QI/Sn/Py/CC if you flash BIOS from version dated 2003/11/27 or older. 2. USB S3 Resume Feature might not alway work in this version of BIOS.

Device: Name: Released: System:	DFI LANPARTY NFII ULTRA B BIOS 19 Jun 2004
File:	N24LD619.BIN (LPNF26191.zip)
Description:	Remarks: 1. Please give instruction "AWDFLASH N24LD619.BIN /QI/CC/Sn/Py" upon flashing BIOS. 2. "Load Optimized Defaults" will be required after completing the BIOS flashing and before entering Windows OS since this version is overall renewed. Major Reaons for Change: To solve the occasionally auto reboot issue. To solve the cold-boot bug. To solve the Bug of S3 Resuming. To Support "Boot Menu" feature. To include the micro codes of mobile CPUs. To add new RAID BIOS of Sil 3114 in version 5.0.35.

Device: Name: Released: System:	DFI LANPARTY NFII ULTRA B BIOS 27 Nov 2003
File:	N24LDB27.BIN (LPNFIIULB1127.ZIP)
Description:	1. To enhance the stability when resuming from S1 mode. 2. To exterminate the CMOS checksum error message after running Memtest 8b and press ESC key. 3. To remove the option item of MIDI in BIOS. 4. To well detect Affery CD-ROM.

Device: Name: Released: System:	DFI LANPARTY NFII ULTRA B BIOS 15 Oct 2003
File:	6A61BD4E.BIN (LPNFIIULB1015.ZIP)
Description:	1. Solve the bug of boot-up failure after clearing the CMOS. 2. To revise the feature of auto backup of CMOS only whenever there's change in BIOS.
Device:	DEI LANPARTY NEII ULTRA B

Device:	DFI LANPARTY NFII ULTRA B
Name:	BIOS
Released:	30 Sep 2003
System:	
File:	6A61BD4E.BIN (LPNFIIULB0930.ZIP)
Description:	First Release