

BIOS Revision History

Bios name	Remarks
FX41S016	Checksum: 7900H 10/18/2002 Initial release
FX41S022	Checksum: 4400H 05/12/2003 1. Fixed Sandra2003 internal AGP mode only show 2x. 2. Fixed can't boot from TEAC USB-CDrom. 3. Adjust fan setting. 4. Fixed enter Win98 DOS mode, screen is blank. 5. Improve 3D performance.
FX41S025	Checksum: A100 09/08/2003 1. Support Thorton CPU, L2 cache is 256K. 2. Support Duron FSB133, L2 cache is 64K CPU (Applebred). 3. Add fan speed function 'Ultra Low, Low, Middle, High'
FX41S026	Checksum: 8B00 12/08/2003 1. Support Duron 1.3GHz Palomino CPU

Close this window