

SCAT EXTENDED SETUP PROGRAM Ver - 1.

	BITS 7 - 0						
82C235	01H	->	RR	00	00	0	0
	41H	->	R 0	RRR	0	00	
	44H	->	R 0	0 0	0 0	0 R	
	46H	->	0 0	RR	00	00	
	48H	->	1 1	0 0	0 0	0 0	
	49H	->	0 0	0 0	0 0	0 0	
	4AH	->	0 0	0 0	0 0	0 0	
	4BH	->	0 0	0 0	0 0	0 0	
	4CH	->	0 0	0 0	0 0	0 0	
	4DH	->	R R	00		1001	
	4EH	->	0 R	0 R		0100	
	4FH	->	1 1	RRRRR		0	